

[illegible][illegible]

SITUAȚIE EXISTENTĂ

The existing facade drawing shows a building section with a grid of windows. The elevation levels are indicated on the right side: +14.06m, +10.80m, +8.10m, +5.40m, +2.70m, ±0.00m, and -1.45m. A ground level marker of -2.50m is shown at the bottom left.

SITUAȚIE PROPUȘĂ

The proposed facade drawing includes technical annotations such as "Balustradă metalică de protecție", "termoizolație stic cu polistiren expandat ignifugat de 10 cm grosime", "Termoisolatam cu polistiren expandat ignifugat 10 cm grosime finisaj tencuieli decorative", and "termoizolație sticlă cu polistiren extrudat ignifugat de 10 cm grosime până la 30cm sub nivelul acului". The elevation levels are identical to the existing drawing: +14.06m, +10.80m, +8.10m, +5.40m, +2.70m, ±0.00m, and -1.45m. A ground level marker of -2.50m is shown at the bottom left.

Verificator/ Expert	Nume	Semnătura	Cerința	Referat / Expertiză Nr. / Data
S.C.HACHIKO DESIGN S.R.L J 40 / 2127 / 2010 str. DINU VINTILA nr. 11, et.8,cam 8,sector 2				BENEFICIAR: Primaria Sectorului 6
				Proiect nr.: 25/2011
Specificatie	NUME	Semnatura	Scara: 1:100	Titlu proiect: Expertiza tehnica, Audit energetic, DALI+DTAC+PT+CS+DE, Verificare si Asistentia tehnica pt.lucrările de reabilitare termica 273 blocuri, Sector 6, Bucuresti Bl. A30, Str. TIMISUL DE SUS, nr.30
Şef proiect	arh. Luminița POPESCU			
Proiectat	teh. Ana DAVID		Data:	Titlul planșei: FATADA LATERALA STANGA SITUATIE EXISTENTA / SITUAȚIE PROPUSA
Desenat	teh. Ana DAVID		2011	

A3